



Manhole Inspection Form

M1-3-3-6



Manhole Number	M1-3-3-6	Historic Manhole Number	Rosebriar 6
Year Installed	1992	Structure Type	Sanitary Manhole
Street	Rosebriar	Address	26175
Elevation	592.107	Weather	Sunny
Temperature	20°	Ground Condition	Dry
Status	At Surface Grade	Location	Yard Front
Pavment Condition	<null>	Traffic	No Traffic at Location
Inspector 1	Brs	Inspector 2	Kmd
Cover Type	Ej1040a	Number of Cover Holes	Solid Cover
Catch Basin Cover	<null>	Cover Insert	No
Cover Gasket	Yes	Cover Grade	Cover is Below Grade
Grade Dist	6	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Fair
Frame Offset	5	Frame Seal Condition	Poor
Frame Seal Inflow	Low	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	9.75
Chimney Depth	1.2	Chimney Construction	Precast
Chimney Condition	Fair	Chimney Inflow	Low
Cone Shape	Eccentric	Cone Depth	28
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	Low	Cone Defect Location	Wall/Cone Joint
Wall Construction	Precast	Wall Condition	Fair
Wall Inflow	Low	Wall Defect Location	Wall Joint +
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Fair
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Fair	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Yes



Manhole Inspection Form

M1-3-3-6



Step Construction	Plastic	Step Condition	Good
Surcharge Evidence	<null>		
Pipe 1 Flow	Outward Flow	Pipe 1 Diameter	8
Pipe 1 Direction	E	Pipe 1 Depth	9.75
Pipe 1 Material	Truss	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	<null>	Pipe 2 Diameter	<null>
Pipe 2 Direction	<null>	Pipe 2 Depth	<null>
Pipe 2 Material	<null>	Pipe 2 Seal Condition	<null>
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Internal Chimney Seal	Recommendation 2	<null>
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>



Manhole Inspection Form

M1-3-3-6



Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	3 – Failure likely in 10 to 20 years (Fair)	Comments	Buried 6"



Manhole Inspection Form

M1-3-3-6





Manhole Inspection Form

M1-3-3-6






Manhole Inspection Form

M1-3-3-6





Manhole Inspection Form

M1-3-3-6



Civil Engineers - Surveyors - Architects 360-720-1254 Page: 3

Date: 12/14/16

Address: 26175 Rosebriar

R.T. = 9.75'

D = 48"

Map: 52

Manhole Number: M1-3-3-6

Community: Chesterfield

Inspector Initials: KMD / BRS

12.25' 3.20
-2.50 -2.50
9.75 0.70


5" offset

1.20'

28"

E
8" Truss
G
9.75'

1/2016 7:08:25 AM



Manhole Inspection Form

M1-3-3-6

