


Manhole Inspection Form

M1-5-3-3-3-2-2-1



Manhole Number	M1-5-3-3-3-2-2-1	Historic Manhole Number	Norvell 1
Year Installed	1980	Structure Type	Sanitary Manhole
Street	Norvell	Address	25861
Elevation	591.33	Weather	Sunny
Temperature	70°	Ground Condition	Dry
Status	At Surface Grade	Location	Driveway Concrete
Pavment Condition	Good	Traffic	Driveway
Inspector 1	Pfm	Inspector 2	Kja
Cover Type	Ej 1040	Number of Cover Holes	Solid Cover
Catch Basin Cover	<null>	Cover Insert	No
Cover Gasket	Yes	Cover Grade	Cover is At Grade
Grade Dist	0	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	2	Frame Seal Condition	Fair
Frame Seal Inflow	Low	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	12.4
Chimney Depth	0	Chimney Construction	None
Chimney Condition	<null>	Chimney Inflow	<null>
Cone Shape	Eccentric	Cone Depth	30
Cone Construction	Precast	Cone Condition	Fair
Cone Inflow	Low	Cone Defect Location	Wall/Cone Joint
Wall Construction	Precast	Wall Condition	Fair
Wall Inflow	None	Wall Defect Location	<null>
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Yes




Manhole Inspection Form

M1-5-3-3-3-2-2-1



Step Construction	Plastic	Step Condition	Good
Surcharge Evidence	<null>		
Pipe 1 Flow	Outward Flow	Pipe 1 Diameter	10
Pipe 1 Direction	E	Pipe 1 Depth	12.4
Pipe 1 Material	ABS	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Inward Flow	Pipe 2 Diameter	10
Pipe 2 Direction	W	Pipe 2 Depth	12.4
Pipe 2 Material	ABS	Pipe 2 Seal Condition	Good
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Internal Chimney Seal	Recommendation 2	<null>
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>




Manhole Inspection Form

M1-5-3-3-3-2-2-1



Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	<null>



Manhole Inspection Form

M1-5-3-3-3-2-2-1

