


# Manhole Inspection Form

M1-30-51-3-2



Manhole Number	M1-30-51-3-2	Historic Manhole Number	Colette 2
Year Installed	1995	Structure Type	Sanitary Manhole
Street	Colette	Address	53824
Elevation	627.684	Weather	Sunny
Temperature	35°	Ground Condition	Dry
Status	At Surface Grade	Location	Yard Front
Pavment Condition	<null>	Traffic	<null>
Inspector 1	Brs	Inspector 2	Kmd
Cover Type	Ej1040apt	Number of Cover Holes	Solid Cover
Catch Basin Cover	<null>	Cover Insert	No
Cover Gasket	Yes	Cover Grade	Cover is At Grade
Grade Dist	0	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	None	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	8.3
Chimney Depth	0.5	Chimney Construction	Precast
Chimney Condition	Good	Chimney Inflow	None
Cone Shape	Eccentric	Cone Depth	38
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	None	Cone Defect Location	<null>
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	<null>	Wall Defect Location	<null>
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	N/A	Channel Exposure	Yes




# Manhole Inspection Form

M1-30-51-3-2



Step Construction	Plastic	Step Condition	Good
Surcharge Evidence	<null>		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	12
Pipe 1 Direction	N	Pipe 1 Depth	8.3
Pipe 1 Material	Truss	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Outward Flow	Pipe 2 Diameter	12
Pipe 2 Direction	S	Pipe 2 Depth	8.3
Pipe 2 Material	Truss	Pipe 2 Seal Condition	Good
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	<null>	Recommendation 2	<null>
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>




# Manhole Inspection Form

M1-30-51-3-2




Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	Truss pipe



# Manhole Inspection Form

M1-30-51-3-2






# Manhole Inspection Form

M1-30-51-3-2





# Manhole Inspection Form

M1-30-51-3-2



51301 Schoenherr Road, St. Clair Township, Michigan 48315  
Civil Engineers • Surveyors 586-726-1234


Date: 11/22/16  
Address: 53824 Glette Ct  
R.T. = 48.30'  
D = 48"  
Map: 11

Manhole Number: M1-30-51-3-2  
Community: City of St. Clair  
Inspector Initials: KMD / BRS

N Truss 12"  
8.30' G

S Truss 12"  
8.30' G

4/2016 7:10:06 AM



# Manhole Inspection Form

M1-30-51-3-2

