



# Manhole Inspection Form

M2-16-25-5-P4-17-4E



Manhole Number	M2-16-25-5-P4-17-4E	Historic Manhole Number	23 Mile 34B
Year Installed	1975	Structure Type	Sanitary Manhole
Street	23 Mile Rd	Address	30650
Elevation	590.876	Weather	Overcast
Temperature	60°	Ground Condition	Dry
Status	At Surface Grade	Location	Paved Concrete
Pavment Condition	Good	Traffic	Two Lane Road
Inspector 1	Kmd	Inspector 2	Kja
Cover Type	EJ	Number of Cover Holes	Solid Cover
Catch Basin Cover	<null>	Cover Insert	No
Cover Gasket	<null>	Cover Grade	Cover is At Grade
Grade Dist	0	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	Low	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	16.65
Chimney Depth	0.5	Chimney Construction	Precast
Chimney Condition	Poor	Chimney Inflow	Low
Cone Shape	Eccentric	Cone Depth	30
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	Low	Cone Defect Location	Wall/Cone Joint
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	<null>	Wall Defect Location	<null>
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Yes



# Manhole Inspection Form

M2-16-25-5-P4-17-4E



Step Construction	Iron	Step Condition	Poor
Surcharge Evidence	0		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	15
Pipe 1 Direction	SE	Pipe 1 Depth	16.6
Pipe 1 Material	Concrete	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Inward Flow	Pipe 2 Diameter	<null>
Pipe 2 Direction	S	Pipe 2 Depth	<null>
Pipe 2 Material	ABS	Pipe 2 Seal Condition	Good
Pipe 2 Drop	Interior	Pipe 2 Comments	Enters structure at 11.85 t/p as 12"
Pipe 3 Flow	Outward Flow	Pipe 3 Diameter	15
Pipe 3 Direction	NW	Pipe 3 Depth	16.65
Pipe 3 Material	Concrete	Pipe 3 Seal Condition	Good
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Seal Wall Joints	Recommendation 2	Internal Chimney Seal
Recommendation 3	<null>	Recommendation 4	<null>



# Manhole Inspection Form

M2-16-25-5-P4-17-4E



Recommendation 5	<null>	Recommendation 6	<null>
Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	<null>



# Manhole Inspection Form

M2-16-25-5-P4-17-4E






# Manhole Inspection Form

M2-16-25-5-P4-17-4E





# Manhole Inspection Form

M2-16-25-5-P4-17-4E

