



# Manhole Inspection Form

M2-16-36-P5-2W-1



Manhole Number	M2-16-36-P5-2W-1	Historic Manhole Number	Sugarbush 2
Year Installed	1971	Structure Type	Sanitary Manhole
Street	Callens	Address	48515
Elevation	584.406	Weather	Sunny
Temperature	55°	Ground Condition	Damp
Status	Not Found	Location	Ditch
Pavment Condition	N/A	Traffic	Two Lane Road
Inspector 1	Jef	Inspector 2	Amc
Cover Type	EJ 1040APT	Number of Cover Holes	Solid Cover
Catch Basin Cover	N/A	Cover Insert	No
Cover Gasket	Yes	Cover Grade	Cover is At Grade
Grade Dist	<null>	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	None	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	9.95
Chimney Depth	0.6	Chimney Construction	Precast
Chimney Condition	Fair	Chimney Inflow	Low
Cone Shape	<null>	Cone Depth	30
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	Low	Cone Defect Location	None
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	None	Wall Defect Location	<null>
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Fully



# Manhole Inspection Form

M2-16-36-P5-2W-1



Step Construction	Iron	Step Condition	Fair
Surcharge Evidence	<null>		
Pipe 1 Flow	Outward Flow	Pipe 1 Diameter	12
Pipe 1 Direction	W	Pipe 1 Depth	9.95
Pipe 1 Material	Concrete	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	<null>	Pipe 2 Diameter	<null>
Pipe 2 Direction	<null>	Pipe 2 Depth	<null>
Pipe 2 Material	<null>	Pipe 2 Seal Condition	<null>
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Internal Chimney Seal	Recommendation 2	Raise
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>



# Manhole Inspection Form

M2-16-36-P5-2W-1



Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	<null>




# Manhole Inspection Form

M2-16-36-P5-2W-1








# Manhole Inspection Form

M2-16-36-P5-2W-1



Civil Engineers • Surveyors • Architects 586-726-1234 Page: 1

Date: 7/13/17  
Address: 48515 Sugarbush  
R.T. = 9.95  
D = 48"  
Map: 25

Manhole Number: M2-16-36-P5-2W-1  
Community: Chesterfield  
Inspector Initials: AMC/JEF

ESB40APT

12" CONC. 9.95' 6

0.6'  
30"  
48"

INSPECT.DWG Layout: Model 6/4/2016 7:08:25 AM



# Manhole Inspection Form

M2-16-36-P5-2W-1







# Manhole Inspection Form

M2-16-36-P5-2W-1

