




# Manhole Inspection Form

M2-16-36-P5-3W-8



Manhole Number	M2-16-36-P5-3W-8	Historic Manhole Number	Peggy 8
Year Installed	1971	Structure Type	Sanitary Manhole
Street	Peggy	Address	50336
Elevation	588.612	Weather	Sunny
Temperature	65°	Ground Condition	Dry
Status	At Surface Grade	Location	Yard Front
Pavment Condition	N/A	Traffic	No Traffic at Location
Inspector 1	Rbc	Inspector 2	Cad
Cover Type	EJ 1040APT	Number of Cover Holes	3 - 5
Catch Basin Cover	N/A	Cover Insert	No
Cover Gasket	Yes	Cover Grade	Cover is Below Grade
Grade Dist	4	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	None	Frame Riser	Yes
Frame Riser Height	8	Frame Riser Material	Concrete
Manhole Diameter	48	Manhole Depth	10.25
Chimney Depth	<null>	Chimney Construction	Precast
Chimney Condition	Good	Chimney Inflow	None
Cone Shape	<null>	Cone Depth	<null>
Cone Construction	Precast	Cone Condition	Fair
Cone Inflow	Low	Cone Defect Location	Wall/Cone Joint
Wall Construction	Precast	Wall Condition	Fair
Wall Inflow	Low	Wall Defect Location	Lift Holes
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Fair	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Fully




# Manhole Inspection Form

M2-16-36-P5-3W-8



Step Construction	Iron	Step Condition	Poor
Surcharge Evidence	<null>		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	12
Pipe 1 Direction	N	Pipe 1 Depth	10.25
Pipe 1 Material	Concrete	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Outward Flow	Pipe 2 Diameter	12
Pipe 2 Direction	S	Pipe 2 Depth	10.25
Pipe 2 Material	Concrete	Pipe 2 Seal Condition	Good
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Vactor Clean	Recommendation 2	Internal Chimney Seal
Recommendation 3	Point Pipes	Recommendation 4	Seal Wall Joints
Recommendation 5	Seal Lift Holes	Recommendation 6	Raise




# Manhole Inspection Form

M2-16-36-P5-3W-8



Recommendation 7	<null>	Recommendation 8	<null>
------------------	--------	------------------	--------


Manhole Rating	3 – Failure likely in 10 to 20 years (Fair)	Comments	
----------------	--	----------	--



# Manhole Inspection Form

M2-16-36-P5-3W-8






# Manhole Inspection Form

M2-16-36-P5-3W-8



51301 Schoenherr Road, Shelby Township, Michigan 48315  
Civil Engineers • Surveyors • Architects 586-726-1234

Page: 6





Date: 6-28-17  
Address: 50336 Peggy  
R.T. = 10.25'  
D = 48"  
Map: 47



Manhole Number: M2-16-36-P5-3W-8

Community: Chesterfield

Inspector Initials: CAD / RBC



2016/06/28 10:08:23 AM

Photograph This Document!

Fax 586-726-8780

Engineering Strong Communities

www.aewinc.com





# Manhole Inspection Form

M2-16-36-P5-3W-8







# Manhole Inspection Form

M2-16-36-P5-3W-8

