



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-9-4-1



Manhole Number	M2-16-36-P5-10E-P6-23-9-4-1	Historic Manhole Number	Laurel Oak 4
Year Installed	1979	Structure Type	Sanitary Manhole
Street	Laurel Oak	Address	51852
Elevation	590.048	Weather	Overcast
Temperature	35°	Ground Condition	Damp
Status	At Surface Grade	Location	Yard Front
Pavment Condition	N/A	Traffic	Two Lane Road
Inspector 1	Kmd	Inspector 2	Brs
Cover Type	EJ pt1040a	Number of Cover Holes	Solid Cover
Catch Basin Cover	N/A	Cover Insert	No
Cover Gasket	Yes	Cover Grade	Cover is At Grade
Grade Dist	0	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	None	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	10.7
Chimney Depth	1.1	Chimney Construction	Combination- S.C.
Chimney Condition	Good	Chimney Inflow	Low
Cone Shape	Eccentric	Cone Depth	24
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	None	Cone Defect Location	None
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	None	Wall Defect Location	None
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Yes



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-9-4-1



Step Construction	Plastic	Step Condition	Good
Surcharge Evidence	<null>		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	12
Pipe 1 Direction	S	Pipe 1 Depth	10.7
Pipe 1 Material	Truss	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Outward Flow	Pipe 2 Diameter	12
Pipe 2 Direction	N	Pipe 2 Depth	10.6
Pipe 2 Material	Truss	Pipe 2 Seal Condition	Good
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Internal Chimney Seal	Recommendation 2	<null>
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-9-4-1




Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	Precast and block chimney. Recently raised.



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-9-4-1





# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-9-4-1






# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-9-4-1






# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-9-4-1





# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-9-4-1

