



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-17-7-7



Manhole Number	M2-16-36-P5-10E-P6-23-17-7-7	Historic Manhole Number	Overlook 5
Year Installed	1987	Structure Type	Sanitary Manhole
Street	Fairway vista	Address	33323
Elevation	594.69	Weather	Sunny
Temperature	45°	Ground Condition	Wet
Status	At Surface Grade	Location	<null>
Pavment Condition	<null>	Traffic	<null>
Inspector 1	Brs	Inspector 2	Kmd
Cover Type	<null>	Number of Cover Holes	<null>
Catch Basin Cover	<null>	Cover Insert	No
Cover Gasket	<null>	Cover Grade	Cover is At Grade
Grade Dist	0	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	<null>
Frame Seal Inflow	<null>	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	10.1
Chimney Depth	0.6	Chimney Construction	Precast
Chimney Condition	Good	Chimney Inflow	None
Cone Shape	Eccentric	Cone Depth	29
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	None	Cone Defect Location	<null>
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	None	Wall Defect Location	<null>
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Yes



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-17-7-7



Step Construction	Plastic	Step Condition	Good
Surcharge Evidence	<null>		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	10
Pipe 1 Direction	NW	Pipe 1 Depth	10.1
Pipe 1 Material	Truss	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Outward Flow	Pipe 2 Diameter	10
Pipe 2 Direction	SE	Pipe 2 Depth	10.1
Pipe 2 Material	Truss	Pipe 2 Seal Condition	Good
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	<null>	Recommendation 2	<null>
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-17-7-7



Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	Under yard swing (fenced in 7-24-2017)



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-17-7-7






# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-17-7-7





# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-17-7-7



1504 Sencott Road, Shelby Township, Michigan 48068  
Civil Engineers • Surveyors • Architects 586-726-1234 Page: 10


Date: 11/22/16  
Address: 33323 Fairway  
R.T. = 10.10'  
D = 48"  
Map: 18

Manhole Number: M2-16-36-P5-10E-16-23-17-7-7  
Community: Chesterfield  
Inspector Initials: KMD / BRS

Nw 10" Truss  
10.10 G

SE 10" Truss  
10.10 G

4/2016 7:10:08 AM



# Manhole Inspection Form

M2-16-36-P5-10E-P6-23-17-7-7

