

Manhole Inspection Form

M2-16-36-P5-6E-13-3W-1



Manhole Number	M2-16-36-P5-6E-13-3W-1	Historic Manhole Number	Seaview 4
Year Installed	1974	Structure Type	Sanitary Manhole
Street	Breezeway (Seaview condos)	Address	31796
Elevation	589.6	Weather	Overcast
Temperature	50°	Ground Condition	Damp
Status	At Surface Grade	Location	Driveway Concrete
Pavment Condition	Poor	Traffic	Parking Lot
Inspector 1	Kmd	Inspector 2	Brs
Cover Type	EJ pt1040a	Number of Cover Holes	Solid Cover
Catch Basin Cover	N/A	Cover Insert	No
Cover Gasket	No	Cover Grade	Cover is At Grade
Grade Dist	0	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	None	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	11.35
Chimney Depth	0.55	Chimney Construction	Precast
Chimney Condition	Good	Chimney Inflow	None
Cone Shape	Eccentric	Cone Depth	30
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	None	Cone Defect Location	None
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	None	Wall Defect Location	None
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Yes



Manhole Inspection Form

M2-16-36-P5-6E-13-3W-1



Step Construction	Plastic	Step Condition	Good
Surcharge Evidence	<null>		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	10
Pipe 1 Direction	W	Pipe 1 Depth	11.35
Pipe 1 Material	Truss	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Outward Flow	Pipe 2 Diameter	10
Pipe 2 Direction	N	Pipe 2 Depth	11.35
Pipe 2 Material	Truss	Pipe 2 Seal Condition	Good
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	<null>	Recommendation 2	<null>
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>



Manhole Inspection Form

M2-16-36-P5-6E-13-3W-1



Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	<null>



Manhole Inspection Form

M2-16-36-P5-6E-13-3W-1



ANDERSON, ECKERT & STRICK, INC.
51301 Schoenherr Road, Shelby Township, Michigan 48315
Civil Engineers • Surveyors • Architects 586-726-1234

Page: 1

M2-16-36-P5-6E-13-3W-1
Manhole Number:

Community: Chesterfield

Inspector Initials: BES / KMD

Date: 11-29-16

Address: 31796 Blossing

R.T. = 11.35

D = 48"

Map: 26

12.25
11.35

10" TRUSS
11.35

(G)
N. TRUSS
10" 11.35

1.80

.55

30

Photograph This Document!

Fax 586-726-8780 Engineering Strong Communities www.aewoc.com


© LUMBERVILLE ENGINEERING - INSPECTORS Layout: Model: 8/4/2016 7:08:23 AM



Manhole Inspection Form

M2-16-36-P5-6E-13-3W-1






Manhole Inspection Form

M2-16-36-P5-6E-13-3W-1






Manhole Inspection Form

M2-16-36-P5-6E-13-3W-1





Manhole Inspection Form

M2-16-36-P5-6E-13-3W-1

